

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

676
WNW
1/2-1
0.983 mi.
5192 ft.

**BROOKLYN SCHOOL SPEC. RESID.
424 BAY 44TH STREET
BROOKLYN, NY 11214**

**NY UST U003200576
NY Spills N/A**

**Relative:
Higher**

UST:

**Actual:
11 ft.**

Name: BROOKLYN SCHOOL SPEC. RESID.
Address: 424 BAY 44TH STREET
City,State,Zip: BROOKLYN, NY 11214
Id/Status: 2-603121 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585009.79081
UTM Y: 4493398.41178
Site Type: School

Affiliation Records:

Site Id: 25073
Affiliation Type: Facility Owner
Company Name: BROOKLYN SCHOOL SPEC. CHILDREN
Contact Type: Not reported
Contact Name: Not reported
Address1: 424 BAY 44TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11214
Country Code: 001
Phone: (718) 946-9700
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 25073
Affiliation Type: Mail Contact
Company Name: BROOKLYN SCHOOL SPECIAL CHILDREN
Contact Type: Not reported
Contact Name: MR. WILLIAM WALSH
Address1: 424 BAY 44TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11214
Country Code: 001
Phone: (718) 946-9700
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 25073
Affiliation Type: Facility Operator
Company Name: BROOKLYN SCHOOL SPEC. RESID.
Contact Type: Not reported
Contact Name: CARLOS
Address1: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 946-9700
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 25073
Affiliation Type: Emergency Contact
Company Name: BROOKLYN SCHOOL SPEC. CHILDREN
Contact Type: Not reported
Contact Name: CARLOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 777-2888
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 1
Tank ID: 53144
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 07/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

SPILLS:

Name: POLE 65948
Address: 424 BAY 44TH STREET
City, State, Zip: BROOKLYN, NY
Spill Number/Closed Date: 9912290 / 2002-03-19
Facility ID: 9912290
Facility Type: ER
DER Facility ID: 165042
Site ID: 198304
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2000-01-26
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-01-26
CID: 389
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-01-26
Spill Record Last Update: 2002-03-19
Spiller Name: CALLER
Spiller Company: CON ED
Spiller Address: 4 IRVING PL
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "

Remarks: "caller reporting a spill of material onto ground tag from manufacturer plate stated <1ppm crews dispatched for clean up coned#129743 "

All Materials:

Site ID: 198304
Operable Unit ID: 1086823
Operable Unit: 01

Material ID: 294178
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00
Oxygenate: Not reported